



Corrosion Resistance Performance of Supplied Parts Exposed To Neutral Salt Spray Conditions

TSR 140363
Account Manager Frank Mula
Date 28th October 2014
Customer GERSHWIN P/L
Aim To determine the corrosion resistance performance of the supplied parts in Neutral Salt Spray for 1000 hours or until failure.
Method AS 2331.3.1 – 2001 Method 3.1: Corrosion and related property tests - Neutral Salt Spray test (NSS).
Component/s 1 x ForceField window assembly
Pre-treatment Chrome-free
Powder Duralloy Pearl White Gloss 272-81880

Part 140363/1

Test	Description	Specification	Result	Pass/Fail
Initial Film Properties	Film Build	Range per 272 TDS: 50 – 100 µm Recommended : 80 µm	46 – 90 microns	Pass
	Initial Adhesion	Classification 1 max.	0	Pass
	Solvent Resistance/Cure	Slight softening &/or marking	Slight marking only	Pass

Results **At hours listed**

140363/1

Test	Description	Specification	Result	Pass/Fail
Corrosion Resistance	Adhesion	Classification 1 max.	0	Pass
	Blistering – general area	Size (S) 2, Density (D) 2 max.	0	Pass
	Blistering – scribed area	Size (S) 2, Density (D) 2 max.	0	Pass
Neutral Salt Spray	Corrosion – general area	No visible corrosion	No visible corrosion	Pass
	Corrosion - filiform Mean Creep from scribe	Note severity & distance from scribe &/or panel edge Mean Creep - 2 mm max.	No filiform corrosion 0	Pass

Conclusion:

Initial film properties tested indicate that all pieces passed for adhesion, solvent resistance and film builds, except that there were a few regions on the frames that had areas of low film build. All parts have passed 1000 hours Neutral Salt Spray exposure with no surface defects in the scribed or general areas.

Brigid Fahey

Technical Officer – Powder Coatings R&D

"This report is provided in good faith by DuluxGroup Ltd ("**DuluxGroup**"), for the sole consideration and use of the recipient and on the understanding and expectation that it will not be relied upon by any other person or organisation. No responsibility or duty toward any other person or entity is assumed, expressly or by implication, by DuluxGroup or by any of its related or subsidiary entities.

In preparing this report, DuluxGroup has relied upon information provided and requirements communicated to it by the recipient, but is not able to anticipate or control the circumstances and conditions under which the recipient may rely upon the report. Accordingly, DuluxGroup on behalf of itself and its subsidiary and related entities, expressly disclaims, to the fullest extent permitted by law, any liability of whatever nature and however arising, including by reason of any actual or alleged negligence on the part of DuluxGroup and/or its related or subsidiary entities, servants or agents, directly or indirectly out of or in connection with its provision of the report and/or reliance upon the report by the recipient or by any other person, entity or organisation.

No express or implied warranties are given except to the minimum extent provided by law. The total liability of DuluxGroup, its related or subsidiary entities, in respect of all matters directly or indirectly arising out of or in connection with the provision of the report or the reliance upon it by any person, entity or organisation, shall not exceed the amount paid or payable to DuluxGroup as consideration for the provision of the report."

Appendix: Photographs – NSS ForceField window assembly

